

This document addresses known errata and documentation issues for the Reed-Solomon Compiler version 7.1. Errata are functional defects or errors, which may cause the Reed-Solomon Compiler to deviate from published specifications. Documentation issues include errors, unclear descriptions, or omissions from current published specifications or product documents.

Table 1 shows the issues that affect the Reed-Solomon Compiler v7.1.

<i>Table 1. Reed-Solomon Compiler v7.1 Issues</i>	
Issue	Page
No Symbol In IP Toolbench Symbol Window	1
File Summary Does Not List All Generated Files	2



For the most up-to-date errata for this release, refer to the errata sheet on the Altera website:

www.altera.com/literature/es/es_rs_71.pdf

Reed-Solomon Compiler v7.1 Issues

This section describes the Reed-Solomon Compiler v7.1 issues.

No Symbol In IP Toolbench Symbol Window

When you click **Display Symbol**, IP Toolbench does not always display a symbol.

Affected Configurations

This issue affects all configurations.

Design Impact

There is no design impact.

Workaround

To see a symbol, click **Step 1: Parameterize**, click **Finish**, click **Display Symbol**.

Solution Status

This issue will be fixed in a future release of the Reed-Solomon Compiler.

File Summary Does Not List All Generated Files

The file summary on the IP Toolbench Generate window does not always list all the generated files.

Affected Configurations

This issue affects all configurations.

Design Impact

There is no design impact.

Workaround

In the Parameterize window, when you finish parameterizing your variation, do not click **Finish**, just go to IP Toolbench and click **Generate**.

Solution Status

This issue will be fixed in a future release of the Reed-Solomon Compiler.

Contact Information

For more information, contact Altera's mySupport website at www.altera.com/mysupport and click **Create New Service Request**. Choose the **Product Related Request** form.

Revision History

Table 2 shows the revision history for Reed-Solomon Compiler v7.1.

<i>Table 2. Reed-Solomon Compiler v 7.1 Errata Sheet Revision History</i>		
Version	Date	Errata Summary
1.0	May 2007	First release.



101 Innovation Drive
San Jose, CA 95134
(408) 544-7000
www.altera.com
Applications Hotline:
(800) 800-EPLD
Literature Services:
literature@altera.com

Copyright © 2007 Altera Corporation. All rights reserved. Altera, The Programmable Solutions Company, the stylized Altera logo, specific device designations, and all other words and logos that are identified as trademarks and/or service marks are, unless noted otherwise, the trademarks and service marks of Altera Corporation in the U.S. and other countries. All other product or service names are the property of their respective holders. Altera products are protected under numerous U.S. and foreign patents and pending applications, maskwork rights, and copyrights. Altera warrants performance of its semiconductor products to current specifications in accordance with Altera's standard warranty, but reserves the right to make changes to any products and services at any time without notice. Altera assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Altera Corporation. Altera customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

