



PCI Development Kit Cyclone II Edition

December 2005, Development Kit Version 1.0

Errata Sheet

This document addresses known errata and documentation changes for the PCI Development Kit, Cyclone® II Edition version 1.0.0. Errata are design functional defects or errors. Errata may cause the PCI Development Kit, Cyclone II Edition to deviate from published specifications. Documentation changes include typos, errors, unclear descriptions, or omissions from current published specifications or product documents. These errata and documentation changes or clarifications will be incorporated into an upcoming release of the PCI Development Kit, Cyclone II Edition.

PCI Development Kit, Cyclone II Edition Version 1.0 Issue

Altera has identified that an outdated board schematics file was distributed on the CD with the PCI Development Kit, Cyclone II Edition version 1.0.



For the most up-to-date errata for this release, refer to the errata page on the Altera website:

www.altera.com/literature/es/es_pci_kit_cycii_10.pdf

Outdated Board Schematics File on CD: schem_cii_pcidevbd.pdf

The board schematics file included with the installation CD is outdated, which inaccurately labels some connections on the board.

Affected Configurations

All of the PCI Development Kit, Cyclone II Edition version 1.0.0 CD-ROMs have this issue. The affected file is **schem_cii_pcidevbd.pdf** in the Documentation directory:

```
<installdirectory>\cycloneii_pci_kit-v1.0.0\doc
```

Design Impact

There is no design impact.

Workaround

Download Revision B of the schematic file, [schem_cii_pcidevbd_b.pdf](#), for the PCI Development Kit, Cyclone II Edition from the Altera® FTP site:

ftp://ftp.altera.com/outgoing/devkit/PCI_DK_2C35/schem_cii_pcidevbd_b.pdf

Solution Status

This issue will be fixed in the next release of the PCI Development Kit, Cyclone II Edition.

Contact Information

For more information, contact Altera's mySupport website at www.altera.com/mysupport and click **Create New Service Request**. Choose the **Product Related Request** form.

Revision History

[Table 1](#) shows the revision history for the PCI Development Kit, Cyclone II Edition version 1.0.

Table 1. PCI Development Kit, Cyclone II Edition Errata Sheet Revision History

Version	Date	Errata Summary
1.0	December 2005	Outdated schematic file on CD inaccurately labels some connections when comparing the schematic to the board.



101 Innovation Drive
San Jose, CA 95134
(408) 544-7000
www.altera.com
Applications Hotline:
(800) 800-EPLD
Literature Services:
literature@altera.com

Copyright © 2005 Altera Corporation. All rights reserved. Altera, The Programmable Solutions Company, the stylized Altera logo, specific device designations, and all other words and logos that are identified as trademarks and/or service marks are, unless noted otherwise, the trademarks and service marks of Altera Corporation in the U.S. and other countries. All other product or service names are the property of their respective holders. Altera products are protected under numerous U.S. and foreign patents and pending applications, maskwork rights, and copyrights. Altera warrants performance of its semiconductor products to current specifications in accordance with Altera's standard warranty, but reserves the right to make changes to any products and services at any time without notice. Altera assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Altera Corporation. Altera customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

