



## PRODUCT DISCONTINUANCE NOTIFICATION PDN0315

### Change Description:

Altera will be discontinuing the ordering code listed in Table 1.

### Reason for Change:

EPC16UC88AA was a temporary ordering code and the same part is shipping under EPC16UC88. Thus, EPC16UC88AA is no longer necessary.

### Key Obsolescence Dates:

Date for last order acceptance: December 15, 2004

Date for last Altera shipments: June 15, 2005

### Contact:

Please contact your local Altera® sales representative if you require additional information regarding this discontinuance.

### PRODUCT ORDERING CODES AFFECTED:

**Table 1: Configuration Device Product Ordering Code to Become Obsolete**

Ordering Code	Compatible Substitute
EPC16UC88AA	EPC16UC88