



This document addresses known errata and documentation changes for the DSP Development Kit, Cyclone® II Edition version 1.0.0.

Errata are design functional defects or errors. Errata may cause the board or the designs included with the DSP Development Kit, Cyclone II Edition to deviate from published specifications.

Documentation changes include typos, errors, unclear descriptions or omissions from current published specifications or product documents. These documentation changes or clarifications will be incorporated in an upcoming releases of the DSP Development Kit, Cyclone II Edition.

DSP Development Kit, Cyclone II Edition 1.0.0 Issue

Altera has identified the following issue that affects the DSP Development Kit, Stratix II Edition:

“Some File Names in the FunctionalTest Directory Are Inaccessible on the DSP Development Kit, Cyclone II Edition CD-ROM v1.0.0.” on page 1.

Some File Names in the FunctionalTest Directory Are Inaccessible on the DSP Development Kit, Cyclone II Edition CD-ROM v1.0.0.

Some file names in the **FunctionalTests** directory were accidentally corrupted during file compression. The suffixes of some long named files were inadvertently modified.

Affected Configurations

All of the DSP Development Kit, Cyclone II Edition version 1.0.0 CD-ROMs have this issue. The affected files are in the **FunctionalTests** directory:

```
<installdirectory>\CycloneII_DSP_Kitv1.0.0\Examples  
\HW\Demonstrations\FunctionalTests
```

Design Impact

Some files in the **FunctionalTests** directory are not accessible.

Workaround

Download version 1.0.1 of the DSP Development Kit, Cyclone II Edition from the Altera® FTP site:

```
ftp://ftp.altera.com/outgoing/devkit  
/CycloneII_DSP-v1.0.1_CD.zip
```

Contact Information

For more information, contact Altera's mySupport web site at www.altera.com/mysupport and click **Create New Service Request**. Choose the **Product Related Request** form.

Revision History

Table 1 shows the DSP Development Kit, Cyclone II Edition version 1.0 errata sheet revision history.

Version	Date	Details of Change
1.0	August 2005	"Some File Names in the FunctionalTest Directory Are Inaccessible on the DSP Development Kit, Cyclone II Edition CD-ROM v1.0.0." on page 1.



101 Innovation Drive
San Jose, CA 95134
(408) 544-7000
www.altera.com
Applications Hotline:
(800) 800-EPLD
Literature Services:
literature@altera.com

Copyright © 2005 Altera Corporation. All rights reserved. Altera, The Programmable Solutions Company, the stylized Altera logo, specific device designations, and all other words and logos that are identified as trademarks and/or service marks are, unless noted otherwise, the trademarks and service marks of Altera Corporation in the U.S. and other countries. All other product or service names are the property of their respective holders. Altera products are protected under numerous U.S. and foreign patents and pending applications, maskwork rights, and copyrights. Altera warrants performance of its semiconductor products to current specifications in accordance with Altera's standard warranty, but reserves the right to make changes to any products and services at any time without notice. Altera assumes no responsibility or liability arising out of the application or use of any information, product, or service described herein except as expressly agreed to in writing by Altera Corporation. Altera customers are advised to obtain the latest version of device specifications before relying on any published information and before placing orders for products or services.

